Tel:(0086)317-5122888 Fax:(0086)317-5204566 Web:www.abtersteel.com Add: 2216#,Taida Building, YingbiNorth Road,YunheDistrict,Cangzhou City, Hebei Province,China

INSPECTION Report No.: MIL Issued on: Mar 1 ^s Inspection Time:	92708&92708-B		P.O. No.	
Inspection				
Subject: Customer:	Seamless Tubes			
Address:				
Specification:	ASTM A179	Inspector:	Lin Gaojie	Stamp No:
Visit Summary: Scope of Inspection - Visual inspection. - Dimension inspection. - Packaging and quantity inspection. - Documents review. - Part photo service.				

Results of inspection to MIL 92708&92708-B

Process Verification

1. Visual Inspection

The tubes were good except a little rust on the surface, and the details were as followed:

- 1) Tube ends had squared cut and deburred well;
- 2) One case of tubes were varnished.

Photo attachment as below



For checking

Tel:(0086)317-5122888 **Fax:**(0086)317-5204566 Web:www.abtersteel.com Add: 2216#, Taida Building, YingbiNorth Road, YunheDistrict, Cangzhou City, Hebei Province, China



Varnished surface


2. **Dimension inspection**

We had measured the pipe dimensions and they were all qualified. The detailed data is in the following table.

Size	Inspection Amount / pc	OD / mm	WT / mm	Length / mm
13.7*2.24*3000mm	10	13.70~13.72	2.17~2.27	3008~3010
13.7*2.24*4572mm	10	13.69~13.74	2.12~2.29	4579~4589
17.1*2.31*6000mm	10	17.17~17.20	2.25~2.37	6004~6009

Photo attachment as below

Tel:(0086)317-5122888 **Fax:**(0086)317-5204566 Web:www.abtersteel.com Add: 2216#, Taida Building, YingbiNorth Road, YunheDistrict, Cangzhou City, Hebei Province, China



- 3. Packaging and quantity inspection1) The tubes were put into the plywood case with poly bag after being stuffed with caps;
- 2) The quantity was right. Photo attachment as below



Tel:(0086)317-5122888 Fax:(0086)317-5204566 Web:www.abtersteel.com Add: 2216#,Taida Building, YingbiNorth Road,YunheDistrict,Cangzhou City, Hebei Province,China

- Review of Documentation

The mill provided Material Test Certificate. The mill provided Physical Inspection Report.

Remarks